


Characteristics of Prototype Silicon Sensors for CDF Run2B

K. Hara, U of Tsukuba

summarizing tests done at Tsukuba/Purdue/UNM

- **Prototype – Design and Delivery**
- **Sensor Characteristics (pre-radiation)**
IV, CV, AC scan, DC scan...
comparison with HPK probing
limitations ...
- **Sensor Characteristics (post-radiation)**
- **Charge Up Issue**
- **Summary**

Prototype - Design





Dimensions -
axial: 40.6 x 96.4 mm²
1.2°: 41.1 x 96.4 mm²

- p+n single sided on 6" (two sensors per wafer)
- 256 AC coupled readout strips (75um/80um pitch)
 p+ width = 8 um; Al width by 14 um
- single intermediate strip
- poly-Si bias resistors of 1.5M Ω
- single guard ring

Prototype - Delivery

Prototypes fabricated by Hamamatsu Photonics


- 60 Axial Prototypes (delivered in July 2002)
- 53 Stereo Prototypes (delivered in Oct 2002)



~1/3 of stereo: unusual stains
no apparent effects on sensor performance


Sensor Characterization

- I-V up to 1000V: All
 - C-V: 23+53 (23 axial+53 stereo) used for strip integrity comparison (HPKvsTsukuba)
 - Stability of I-V: 7+9
 - Long-term stability: 6+4 biased at 500V
 - AC scan: Coupl. Cap (Ccp), $\sim R_{bias}$ (R), oxide leak(Icp) : (18+4)+18
 - DC scan: I_{strip} : 0+2, only for leaky sensors
 - Interstrip resistance: 3+0
 - Interstrip capacitance: (9+4)+2 +4: strips sampled covering the full region
- Diagnostic tests when irregularities are found
- **n irradiation:** 3 sensors @ 1.4×10^{14} n/cm²
2 sensors @ 0.7×10^{14} n/cm²




I-V curve

60 axial



53 stereo




IV is good to 1kV
our spec: 500V


C-V curves

(axial)

f=400Hz



(stereo)



C-V curves

Full Depletion Voltage




Fig. 3a C-V curve and evaluation of “the full depletion voltage”. HPK determines (see text) it to be 150V, whereas we obtain 132V for this sensor, stereo #001.

HPK: lowest V_{bias} when $\Delta(1/C^2) < 0.02 (1/C^2)$ @ $V_{\text{step}}=10V$

Correlation of Full Depletion Voltages between HPK and Tsukuba




Fig. 3b Correlation of full depletion voltages defined by HPK and Tsukuba.





Fig. 3c Full depletion voltage distributions for axial and stereo sensors (Tsukuba) and for all (HPK).

good correlation, though HPK gives ~20V larger
our spec: $120V < V_{dep} < 250V$


IV stability (axial)

good ones ...


001 I-V stability




002 I-V stability




005 I-V stability



007 I-V stability




016 I-V stability






IV stability (stereo)


usual ones



two sensors with micro-discharge



IV stability (bad axial)




A032 showed instability at later stages (~7hrs)
breakdown at HV ramping (at 800V after 10hrs)

Out of 16 sensors, we found one bad sensor...

What went wrong with 032?

IR camera view:


clear trace of discharge



junction breakdown: no recovery

We must respect the spec (500V)!?


bias-ring





scratch degrades I-V stability?

some of I-V curves are certainly worse for stereo...

class A



class Bs



DC scan

... only for leaky sensors




Fig. 5 DC scan (stereo #010) measured at 400V

RU225: HPK leaky

DC scan

No leaky strip reported by HPK




Intermediate strip scan




I-V curve for leaky strip


increase in total leakage current is fully explained by this single strip



IU225



AC scan



$R \sim 1.9 \text{M}\Omega$
includes contribution of implant resistance in series (R_{bias} is $0.4 \text{M}\Omega$ smaller)

$C_{cp} \sim 120 \text{pF}$

$I_{cp} \sim 7 \text{nA}$

leakage through relays (~ 0 if relays are not used)
 $\sim 9 \mu\text{A}$ if oxide punch-through

Fig. 4a Example of AC Strip number #068).

Step:
measure C_{cp} - R (relay-on)
apply 100V across C_{cp} for 1s
measure I_{cp} (relay-off)





Figure 3: Setup for the full strip scan (AC scan)

AC scan results (bad examples)


054 axial



RD256
RD249
RD248
RD244

punch-through
Icp is large

023 stereo






RU2 implant open
open is identified with microscope



Interstrip Resistance

Distribution looks different,
but all are $>50\text{G}\Omega$

In addition to these scans, R_{int}
is measured to identify strips
with irregular result...



Interstrip Capacitance



All looked similar except #007
 C_{int}(R5-R6) is high ...
 R5 & R6 showed smaller R






Fig. 7b Interstrip capacitance: Sensor 006 (Stereo) with an irregular value

Intermediate Implant Opens

Examples of Implant Opens



just one case



usual case

sensor	HPK	Tsukuba
1		
2		
5		RU62 (Ccp=93pF, R=1.77MO, Implant open)
7		RD252 (R=1.1MO) RD251 (R=1.1MO) trace of small discharge
10	IU244 (Implant open)	IU244 (R=large)
	IU241 (Implant open)	IU241 (R=large)
	IU126 (Implant open)	IU126 (Implant open)
11	IU183 (Implant open)	IU183 (Implant open)
12		RU240 (Ccp=1.07nF, R=2.94MO, Icp= 8.1uA)
16		
20		RD231 (167pF, 1.45MO, 6uA)
		RD217 (887pF, 2.63MO, 8uA)
21		
23		RD242 (252pF, 3.7MO, 8uA),
		RD241 (149pF, 2.9MO, 8uA)
		RD240 (4860pF, 1.7MO, 8.3uA)
		RD200 (197pF, 3.7MO, 8uA)
		RD194 (155pF, 3.7MO, 8uA), RD116 (1920pF, 2.6MO, 8uA)
26		
53		
54	ID237, ID240 (Leaky strip)	RD256 (129pF, 1.15MO, 8.1uA)
	RD249, RD250 (Leaky strip)	RD249 (120pF, 2.0MO, 1.5uA)
		RD248 (3291pF, 1.6MO, 8.3uA)
		RD244 (292pF, 3.7MO, 8.0uA)
56		
62		
64		
67	ID229, ID230, RD230 (Bad isolation)	RU136 (Ccp=80pF, R=1.6MO, implant open)

Dead Channels:axial summary

small discharge

new & obvious




- open identified with microscope
- resistance of DC pad to B.R. large
- Icp consistent with punch-through

Too many punchthrough created...?

Informed that HPK applied only 100V instead of 120V at punch through test!

new & obvious:
Readout implant opens

almost certainly new:
Discharge at probing!




Dead Channels:stereo summary

ID	HPK	Tsukuba
6		
7	RU225 (Leaky)	
10		RU225 (leaky)
		RU75 (C=55,R=1.16; implant open)
23		RU2 (C=40,R=0.88; implant open)
24		
47	IU158 (Implant open)	IU158 (Implant open)
65	IU59 (Implant open)	IU59 (R=20M)
66	IU238 (Implant open)	IU238 (implant open)
68	IU21 (Implant open)	IU21 (implant open)
69		
13		RD83 (C=111, R=1.77)
46		
49	IU147 (Implant open)	IU147(R=large)
50		
53	ID7 (Implant open)	ID7 (implant open)
		RD24 (C=90,R=1.6, implant open)
57	ID62 (Implant open)	ID62 (implant open)
63	ID146 (Implant open)	ID146 (implant open)
25	ID230 (Implant open)	ID230 (implant open)

No new punch through
since HPK applied 120V!

now at FNAL


Long-term current stability



4 axial + 4 stereo sensors are placed
in an environmental chamber (20degC)

30 AC pads/sensor are wirebonded to
external V to test oxide punch-through
 $V_b = +500V$
 $V_{cp} = +100V$


Long-term stability test: status(1)



No breakdown sensors


One axial (A23) failed oxide stability, as HPK/tested at 100V only

Long-term stability test: status(2)




Coupling capacitor at 120V

Coupling Capacitor Stability Unirradiated Sensor



4 Ccp with 120V applied

Ccp dropped by 1.5% ...



Limitations in HPK probing




Fig. 9 Illustration of measurement configurations of readout and intermediate implant opens. strips measurements.

HPK probing is not sensitive to detect Readout Implant Opens

- DC scans at the poly-Si side


Tsukuba found 5 Readout Implant Opens, but none by HPK*

*HPK revisited their data, but no hint of irregularity found.

HPK tested the same sensor we tested, but failed to identify.


Also ...

Limitation for stereo sensors



Our decision :

We accept un-probed short strips and un-detected implant opens, since the fraction of defect rate **should be** very small.



estimate from total number of defects, which is almost zero.

15 defects / 113 sensors
15 / 58k strips = 0.0026%

Post Irradiation Measurements

expected fluence at CDF: $(0.46 \pm 0.14) \times 10^{14}$ 1-MeV n/cm²/fb⁻¹ @L0

1.4×10^{14} n/cm² for 30 fb⁻¹ @L0 (r=2.1 cm)

3 sensors irradiated to 1.4×10^{14} n/cm² ... Purdue
2 sensors irradiated to 0.7×10^{14} n/cm² ... UNM/Tsukuba

at MNRC Irradiation Facility at UC Davis

measured items:

I-V Curve

C-V Curve

Interstrip Resistance

Interstrip Capacitance




Bias Resistance

Coupling Capacitance

to see if any surprises ...

in practice: not straightforward to
characterize due to
large leakage current...

I-V and Damage Constant (equiv. neutron fluence)





Sensor 69 experienced additional annealing



Using $4 \times 10^{-17} \text{ A/cm}$, $\phi \sim 1.1 \times 10^{14} \text{ n/cm}^2$



I-V and Damage Constant (equiv. neutron fluence)



Using $3 \times 10^{-17} \text{ A/cm}$,
 $\phi = (0.33\text{-}0.64) \times 10^{14} \text{ n/cm}^2$

- No unexpected I-V characteristics
- Damage as expected

C-V and Full Depletion Voltage




Sensor 060: 128V

Sensor 063: 130V



Sensor 01&02: ~50V

Results not inconsistent
with Rose prediction



Poly-silicon Resistance

$1.4 \times 10^{14} \text{ n/cm}^2$



“Resistance” reaches the asymptotic value above $\sim 350\text{V}$ *

“Resistance” is smaller after irradiation


Intrinsic R is not degraded, but we see effects from surface charge

* substantially larger than V_{FD} ($\sim 130\text{V}$)


Interstrip Resistance

$0.7 \times 10^{14} \text{ n/cm}^2$

temperature dependence:




strip uniformity@ -10°C:



Strong temperature dependence due to surface charge
 Bias be $>250\text{V}^*$ at -10°C for $R > 1\text{G}\Omega$
 $*$ substantially larger than V_{FD} ($\sim 50\text{V}$)

Interstrip Capacitance (I)





Shoulders corresponding to the measured full depletion voltage
Asymptotic Cint consistent with pre-irradiation values
Cint decreases slowly above V_{FD}

Interstrip Capacitance (II)

strip uniformity@ -25°C :

$0.7 \times 10^{14} \text{ n/cm}^2$



freq depend. at 300V



LCR freq (1MHz) may be not high enough ...?

Require a bias substantially larger than V_{FD} to reach the asymptotic values

Coupling Capacitance




Coupling Capacitors are OK!

A Consideration ...

For $V < V_{FD}$:

Moderate isolation is achieved

C_{int} is not very large



depleted region


$(V < V_{FD})$

$n+$

$V \gg V_{FD}$ is required to

isolate strips

minimize C_{int}



depleted region


$(V > V_{FD})$

$n+$

Mechanical Precisions


Measuring Microscope : Mitutoyo MF-UA

typ 1-2 μm in XY
typ 3 μm in Z





- Wafer thickness
- Edge cut precision
- Sensor warp

Sensor Planarity



(single side) sensors are bowed due to CTE difference




← typical profile




deviation of 4th fiducial wrt others

height at the center wrt fiducials at 4 corners

Wafer thickness



Edge cut precision



edge cutting is precise to 5 um...


Charge-Up Issue

In early stage, we often got bad distributions (R/Ccp e.g.)

Rint, Cint are also affected

symptom: **isolation degrad.**

From the location and size of bad strips, we suspected vacuum tweezers caused charge-up on sensor surface



After eliminating use of tweezers, only a few “charge-up” channels much less frequently


This could be due to probe tips not properly discharged

After 3 months, it became hard to reproduce charge-up...

anyway... Charge-up disappear if the sensor is back in envelope

Charge Up – its mechanism


<100> is easier than <111> to charge up
due to lower transition potential for inversion layer creation



fixed oxide charges in SiO₂
Si-SiO₂ interface

<111>:

- about one order abundant positive charges
- attracts more electrons, which isolate P+ implants
- stronger against external effects



<100>:


- fewer positive charges
- fewer electrons attracted
- less robust against external effects

may create P layer = inversion layer

Charge Up – recovery

Inversion layer should disappear by radiation
accumulation of positive charges in
oxide layer, which attract more electrons
(> extra holes in inversion layer)



Strips with small R recovered
after n irradiation



Surface charges responsible for inversion layer
creation should be taken away if there is a route

- Al strips are wire-bonded
- substantial surface current

Charge Up – recovery



a sample heavily charged up
 apply epoxy (Araldite 2011)
 some Al strips wire-bonded

- (1) recovery around bonded strips
- (2) no recovery in isolated area for 61h

Charge-Up Recovery (w/ UV)

Bias is kept on at 200V
UV on ($I_b \sim 175\mu\text{A}$)

substantial recovery in the
region close to wire-bonds
(see the time constant)


Unfortunately but...

- probes wiped prior to T=63h measurement
- sensor taken off the stage !

charge-up disappeared...
we terminated data taking

Lessons:

- wire-bonds remove surface charge
- surface charge in isolated area could remain at least for days
- UV enhances charge removal
- avoid use of tweezers unless it is proven not to charge-up



Summary of Prototype Characteristics

Electrical characteristics are OK

- Leakage current is small ($\sim 0.1\mu\text{A}$) and IV good to 1000V
 - Dead channel fraction is small
 - Defects reported by HPK are all identified
 - 5 new readout implant opens are found
 - 1 new un-identified defect
- ← limitation of the HPK test system

Mechanical precisions are OK

Post-irradiation characteristics are OK

- Reasonable full depletion voltages of irradiated samples
- Degradations in Isolation, C_{int} ,... due to surface charge as expected
requires additional bias to recover them

Charge-up: understood & manageable

Important that our QA is sensitive to detect charge-up when it happens

Quality Assurance Procedure

CDF note 6283

Jan.25, 2003 v1

Silicon Sensor Quality Assurance for the CDF Run2b Silicon Detector

N. Bacchetta¹, G. Bolla⁴, D. Bortoletto⁴, A. Canepa⁴, B. Flaughner¹, K. Hara⁶, D-H. Kim⁵,
S. Kim⁶, M. Hoferkamp³, D. Pellett², A. Roy⁴, S. Seidel³, Y. Takei⁶, I. Yu⁵

¹Fermilab, Batavia, Illinois, USA

²University of California, Davis, California, USA

³University of New Mexico, Albuquerque, New Mexico, USA

⁴Purdue University, West Lafayette, Indiana, USA

⁵CDF-Korean Group (Syungpook U, Sungkyunkwan U)

⁶University of Tsukuba, Tsukuba, Ibaraki, Japan

Abstract




This document describes in detail the quality assurance (QA) program for the CDF Run2b silicon sensors. The scope of the QA program, the responsibilities of the participating institutions and the measurement procedures are defined.

Production Schedule: HPK Proposal

6" line is shared with other commercial products

HPK enhances those production till June 2003

HEP production is postponed/slowed down:

CMS  GLAST  (ATLAS  4")

HPK Proposal for CDF order:

	03/06	07	08	09	10	11	12	04/01	02	
axial	135	135	270	270	270	210	275	135	+	= 1700+
stereo	0	0	125	125	0	125	125	190	+	= 690+

Outer axial: 1656

Outer stereo: 648

L0 axial: 144

+ spare: ~20%

QA program: guideline

Clear definition of QA program is essential to achieve effective/efficient QA among several institutions involved.

HPK: lot basis data: R_poly, R_implant
for each sensor: I-V up to 1000V
full depletion voltage (C-V)
visual inspection
for each strip: strip integrity (AC scan/DC scan)
Ccp Isolation (~R_poly)
Al open implant open (interm.)
Al bridge leaky

Institutions:

intensive probing ~ intensive damaging ...
do minimum required: I-V and visual inspection
intensive probing on sensors with irregular I-V

with visual problems
with many defect strips

check HPK's QA



Organization

Procurement and Testing Institutes


- o University of Tsukuba, Japan. Local coordinator: K. Hara
- o Kyunpook National University, Korea. Local coordinator: D-H. Kim

Procurement Institute

- o Fermilab, Batavia, USA. Local coordinator: N. Bacchetta

Testing Institutes

- o University of New Mexico: S. Seidel
- o Purdue University: D. Bortoletto
- o University of California, Davis: D. Pellett



QA program - summary

QA item	QA done by	sampling (production)	Comments	Excel book page
(1) Initial registration	Procur. Inst.	100%		Page-1
(2) Visual Inspection	Procur. Inst.	100%		Page-2
(3) I-V	Procur. Inst.	100%		Page-3
(4) IV-stability	Testing Inst.	30% (5%*)	Sensor subsets	Page-4
(5) AC-scan	Testing Inst.	30% (5% *)	Sensor subsets	Page-5
(6) C-V	Testing Inst.	30% (5% *)	Sensor subsets	Page-6
(7) Mechanical Tests	Testing Inst.	10% (5% *)	Sensor subsets	Page-7
(8) DC-scan	Testing Inst.	10% (5%*)	Diagnostic+subsets	
(9) Poly-Si resistor	Testing Inst.	10% (5% *)	Diagnostic+subsets	
(10) Interstrip Cap.	Testing Inst.	10% (5% *)	Diagnostic+subsets	
(11) Interstrip Res.	Testing Inst.	10% (5% *)	Diagnostic+subsets	
(12) n irradiation	Testing Inst.	3-4 / 2 mon		
(F) IV and Vis. Inspct	Fermilab	100%		Page-1

(2)/(3) will be merged to (F), once quality sensor production is established

*or at least one sensor per batch

Do (9) frequently if it is easier for detecting charge-up

Excel based Database

Sensor package=Excel file name

- (1) Divide package/Excel if required
- (2) Institutes with sensors can update Excel
- (3) All fragments gathered at FNAL

